

PREPARED FOR:

INTERMOUNTAIN POWER SERVICES CORPORATION
DELTA, UTAH
OCTOBER 18, 1999
TLN 357G



dedicated to filtration science . . .

P.O. Box 42537 • Phoenix, AZ 85080 602-582-5155 • Fax 602-581-9264 Laboratory: 2501 W. Behrend Dr., Suite 77 • Phoenix, AZ 85027



October 18, 1999 TLN 357G Page 1

REPORT INTERMOUNTAIN POWER SERVICES CORPORATION

Reference: Unit 2 - TLN 349G

One filter bag sampled from Unit 2 was submitted to address increased pressure differentials.

The bag has been in service for 10 years however experienced the same suspected moisture excursions as the TLN 349G Unit 2 bag recently installed.

This bag specimen exhibited the same general characteristics as the TLN 349G filter bag in that the top zone is higher than the bottom area in permeability acceptances.

All flows are lower than TLN 349G however, the same profile is evident.

Low flow throughput did extend upward to the middle area as compared to only the bottom section of TLN 349G bag.


The as received ash cake structured also revealed this densification characteristic following the same characteristics as TLN 349G.

The top area did contain agglomerations however yielded a higher level of voids, with the structure as compared to the bottom of the bag.

The bottom and middle areas exhibited a denser cake and substantially reduced voids for throughput.

Photo A is a view of the top area revealing the high voids/less dense cake compared to the middle (**Photo B**) and bottom areas (**Photo C**).





Noted is the low voids evident in the densified cake of the middle and bottom area.

Cleaning generated the same continued profile of low flows in the bottom up to the top area where nominal levels are present.

Photo D (top) compared to **Photo E (middle)** and **Photo F (bottom)** are views of this profile of retention corresponding to the flow capacity readings.





Photo D

Photo E



Photo F

All densified dust yielded the hygroscopic calcium sulphate salt as the binder indicative that moisture leaks into the flue gas is responsible for the agglomerate structure and resulting low throughput.

It is reported that sonic assist is in the system.

This sonic impact in the upper bag area may account for the improved flows in the top bag areas of both this bag and the TLN 349G bag.

The sonic power level is reduced/absorbed as it travels down into the compartment for re-claim it is suggested to place horns (portable) for firing near or at the bag bottom area for disruption of the dense cake similar to the upper bag zone.

Sonic power low Hertz (@ 125 db) and high power levels of 140 plus db levels are most effective in breaking up the dense agglomerations.

The sulphate salt bonded nodula are disrupted under 140 plus db power levels.

This bag also exhibited good tensioning levels with no abnormal wear evident resulting from a slack condition.

All current losses are the result of physical fatigue from service use.

There is no chemical or thermal deterioration evident.

The bag is rated at 80% termination indicative of continued 2 years service use.



INTERMOUNTAIN POWER Prepared for:

10/18/1999 Date:

357G TLN:

Page:

Identification: UNIT 1 - 10 YEARS

Fiber Content: FIBERGLASS ECDE

Fabric Construction: WOVEN

Weave: 3 X 1 TWILL

Count:

Yarn System- Warp/Length: 37-1/0F

Filling Width: L75-1/2T+75-1/0F

Avg. Weight [oz/sq yd]: 13.37 Thickness [inches]: .014 Density Factor:

Treatment- Physical Type: NONE

Chemical Type: ACID RESISTANT

% Ignition Loss [LOI] ---> 500°F/1 Hr: 0.03% 1150°F/1 Hr: 3.93%

% Extractable Matter: SULPHATES

Acid Alkaline [PH]: ALKALIN

Fabrication

Seaming: CHAIN


Hardware: CR


Sewing Thread: FIBERGLASS ECB


Cuffing: LOCK Ring Cover:LOCK


Fabrication Rating: GOOD


PROFILE DATA		an and		TOP	CENTER	BOTTOM
on the same of	,	As Rece	ived	24.11	25.17	26.11
		Cleaned	(Vacuum)	19.45	20,63	20.29
		Cleaned	(Washed)	13.37	13.40	13.35
Permeability As re		As rece	ived	3.07	2.20	1.78
CFM/sq ft Cleane		Cleaned	(Vacuum)	8.0	6.4	4.5
@ .5" H2O C1		Cleaned	(Washed)	49.5	46.8	48.8
Breaking	Warp/Leng	th		219	221	174
Strength lbs/inch	Filling/W:	idth		94	95	81
Breaking	Warp/Leng	th	@ 500	56.20%	55.80%	65.20%
Strength % Loss	Filling/W	idth	@ 350	73.14%	72.86%	76.86%
Mullen Burst (lbs/sq inch)			.,	178	180	161
Mullen Burst % Loss			@ 750	76.27%	76.00%	78.53%
		Warp		15079	14483	11009
		Fill	· · · · · · · · · · · · · · · · · · ·	3942	3725	2121
Flex Cycles		Warp	@ 50,000	69.84%	71.03%	77.98%
% Loss Fi		Fill	@ 10,000	60.58%	62.75%	78.79%
Other Testin	g			,	*	
















Co., Inc.

Laboratory:

2501 W. Behrend Drive

Suite 77

Phoenix, Az 85027 P. O. Box 42537

Phoenix, Az 85080

Telephone:

Mailing:

(602) 582-5155

FAX:

602) 581-9264


Ton J	sha No	mar 9	From	Kath.	
	5-864-		Pagasi	rı	
	ntermou		Darter	10-18	
Re:	LN 35-	76			
□ Urgest	☐ For Review	☐ Please Cor	mment [Please Reply	☐ Please Recycle

The formal report copy will be mailed to your attention. Please do not hesitate to contact us if you have any questions about the report.

Thank you for choosing Environmental Consultant Company for your testing needs.

Grub?

M



PREPARED FOR:

INTERMOUNTAIN POWER SERVICES CORPORATION **DELTA, UTAH OCTOBER 18, 1999 TLN 357G**

dedicated to filtration science . . .

P.O. Box 42537 • Phoenix, AZ 85080 602-582-5156 • Fax 602-581-9264 Laboratory; 2501 W. Behrand Dr., Suite 77 • Phoenix, AZ 85027

6025819264

October 18, 1999 **TLN 357G** Page 1

REPORT INTERMOUNTAIN POWER SERVICES CORPORATION

Reference: Unit 2 - TLN 349G

One filter bag sampled from Unit 2 was submitted to address increased pressure differentials.

The bag has been in service for 10 years however experienced the same suspected moisture excursions as the TLN 349G Unit 2 bag recently installed.

This bag specimen exhibited the same general characteristics as the TLN 349G filter bag in that the top zone is higher than the bottom area in permeability acceptances.

All flows are lower than TLN 349G however, the same profile is evident.

Low flow throughput did extend upward to the middle area as compared to only the bottom section of TLN 349G bag.


The as received ash cake structured also revealed this densification characteristic following the same characteristics as TLN 349G.

The top area did contain agglomerations however yielded a higher level of voids, with the structure as compared to the bottom of the bag.

The bottom and middle areas exhibited a denser cake and substantially reduced voids for throughput.

Photo A is a view of the top area revealing the high voids/less dense cake compared to the middle (Photo B) and bottom areas (Photo C).





Noted is the low volds evident in the densified cake of the middle and bottom area.

Cleaning generated the same continued profile of low flows in the bottom up to the top area where nominal levels are present.

Photo D (top) compared to **Photo E (middle)** and **Photo F (bottom)** are views of this profile of retention corresponding to the flow capacity readings.




Photo F

All densified dust yielded the hygroscopic calcium sulphate salt as the binder indicative that moisture leaks into the flue gas is responsible for the agglomerate structure and resulting low throughput.

It is reported that sonic assist is in the system.

This sonic impact in the upper bag area may account for the improved flows in the top bag areas of both this bag and the TLN 349G bag.

The sonic power level is reduced/absorbed as it travels down into the compartment for re-claim it is suggested to place horns (portable) for firing near or at the bag bottom area for disruption of the dense cake similar to the upper bag zone.

Sonic power low Hertz (@ 125 db) and high power levels of 140 plus db levels are most effective in breaking up the dense agglomerations.

The sulphate salt bonded nodula are disrupted under 140 plus db power levels.

This bag also exhibited good tensioning levels with no abnormal wear evident resulting from a slack condition.

All current losses are the result of physical fatique from service use.

There is no chemical or thermal deterioration evident.

The bag is rated at 80% termination indicative of continued 2 years service use.



Prepared for: INTERMOUNTAIN POWER

Date: 10/18/1999

TLN:

Page:

Identification: UNIT 1 - 10 YEARS

Fiber Content: FIBERGLASS ECUE

Fabric Construction: WOVEN Weave: 3 X 1 TWILL

Count:

Yarn System- Warp/Length: 37-1/0F

Filling Width: L75-1/2T+75-1/0F

Avg. Weight [oz/sq yd]: 13.37 Thickness [inches]: .014 Density Factor:

Treatment- Physical Type: NONE

Chemical Type: ACID RESISTANT

% Ignition Loss [LOI] ---> 500°F/1 Hr: 0.03% 1150°F/1 Hr: 3.93%

% Extractable Matter: SULPHATES

Acid Alkaline [PH]: ALKALIN

Fabrication

Flex Cycles

Other Testing

% Loss

Warp

Fill

Hardware: CR

69.84%

60,58%

71.03%

62.75%

Sewing Thread: FIBERGLASS ECB

Seaming: CHAIN Cuffing: LOCK

Fabrication Rating: GOOD Ring Cover:LOCK PROFILE DATA CENTER BOTTOM TOP 26.11 25,17 24.11 As Received 20.29 20.63 19.45 Weight [oz/sq yd] Cleaned (Vacuum) 13.35 13.40 Cleaned (Washed) 13.37 1.78 2.20 Permeability As received 3.07 4.5 6.4 CFM/sq ft Cleaned (Vacuum) 8.0 48.8 ● .5" H2O 46,8 Cleaned (Washed) 49.5 174 221 Breaking Warp/Length 219 Strength lbs/inch Filling/Width 81 95 94 Breaking 65.20% Warp/Length 55.80% 56.20% **@** 500 Strength % Loss 76.86% Filling/Width 73.14% 72.86% **@** 350 Mullen Burst (lbs/sq inch) 161 180 178 Mullen Burst % Loss 78.53% 76.00% 76.27% **@** 750 Flex Cycles 11009 14483 Warp 15079 [MIT Method] Fill 2121 3725 3942

₫ 50,000

@ 10,000

77.98%

78.79%